


FIFI A Study of the Hurricane Damage in Honduras, 1974



G
28

69/3

FIFI

A Study of
the Hurricane Damage
in Honduras, 1974

FOR MEMORANDUM

TO THE DIRECTOR, CENTRAL INTELLIGENCE AGENCY

Contents

Introduction	2
The Cyclone — A Natural Phenomenon	3
Hurricane Fifi	5
Geology, Hydrology and Topography of the Inundation Area	12
Extent of Losses and Damage	14
Lessons for the Future	23
Concluding Remarks	27

Illustrations:

Archives (15)—DPA, Frankfurt (1)—
Günter H. Eckert, Büro für Technische
Grafik, Munich (3)—O. E. Serrano,
San Pedro Sula (8)—Süddeutscher
Verlag, Munich (1)

© 1975 Münchener Rückversicherungs-
Gesellschaft, D-8000 München 40,
Königinstrasse 107, Bundesrepublik
Deutschland

Printed by Karl Thiemig AG, 8 Mün-
chen 90, Pilgersheimer Strasse 38
Printing blocks: A. Gaessler & Co.
GmbH, Chemigraphische Kunstanstalt,
Munich.